



SECRET






FIG. 4


FOURTH STEP



FIFTH STEP



SIXTH STEP




TO SEVENTH STEP


09698185 103000

FIG. 5

SEVENTH STEP



EIGHTH AND NINTH STEP



COMPLETE

09698185-103000

FIG. 6




FIG. 7




FIG. 8




FIG. 9





FIG. 10



09698185-1030000 "SECRET"

FIG. 11







FIG. 12



099315 10300



099315 10300



09698185 1.030000

FIG. 15




FIG. 16




FIG. 17





FIG. 18



00000T "SST86960

FIG. 19







FIG. 20



SECRET



SECRET



09699185-103000 "SECRET"

FIG. 26a





FIG. 26b



059315 100000

FIG. 27




FIG. 28




FIG. 29





FIG. 30






FIG. 33a




FIG. 33b




FIG. 34a




FIG. 34b





FIG. 35



00000155 103000

09698185-1030000

FIG. 36




FIG. 37




FIG. 38




FIG. 39a




FIG. 39b





FIG. 39c



09698185, 1030000

FIG. 40





FIG. 41



PHYSICAL VALUES AND SPUTTER RESISTANCE OF STRESS RELAXATION LAYER CANDIDATE MATERIAL
(X: OCCURRENCE OF CRACKS, Δ : OCCURRENCE OF WRINKLE, \circ : NO ABNORMALITY)